Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division

GPS Map Camera
Bengaluru, KA, India
1st Cross Road, Dodda Bommasandra, Bengaluru, 560097, KA, India
Lat 13.062415°, Long 77.557383°
09/07/2021 12:17 PM

GPS Map Camera
Bengaluru, KA, India
2nd Cross Road, Vidyaranyapura, Bengaluru, 560097, KA, India
Lat 13°3'49"N, Long 77°33'30"E
09/14/2021 03:03 PM

Suretha. N
AE W10

AEE (VRP) SD

Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division

GPS Map Camera
Bengaluru, KA, India
2nd Cross Road, Dodda Bommasandra, Bengaluru, 560097, KA, India
Lat 13°3'46"N, Long 77°33'27"E
09/17/2021 03:33 PM


GPS Map Camera
Bengaluru, KA, India
1st Cross Road, Dodda Bommasandra, Bengaluru, 560097, KA, India
Lat 13°3'44"N, Long 77°33'27"E
09/17/2021 03:38 PM

Sweetha. N R
AE 410

AEE (VRP) SD

Name of Work: Estimate for Providing Missing Covering Slabs at Muneshwar Block,Subbanna Beedi in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division



Sunitha. NL
AE D10

AEE (VRP) SD